



MARTEC

UNI13

ISO 11446

- 1 - L ←
- 2 - Ⓞ
- 3 - Ⓞ
- 4 - R →
- 5 - R Ⓞ
- 6 - STOP
- 7 - L Ⓞ
- 8 - H₂
- 9 - +12V
- 10 - Ⓞ +12V
- 11 - Ⓞ
- 12 - -----
- 13 - Ⓞ

www.dobrehaki.pl